

28 OCT 1963

**SECRET**

OUT52155

SECRET 252134Z

OCT 25 22 00Z

HFS

GJS

GNS

FNS

AGL

25X1

1. CAMERA B 11 WAS USED IN MISSION 3759 FLOWN ON 23 OCTOBER 1963; PROCESSING WAS ACCOMPLISHED BY NAVY PIC.

2. ORIGINAL NEGATIVE:

A. THE RESOLUTION IS GOOD. THE EXPOSURE IS ADEQUATE BUT THE NEGATIVE IS THIN AT THE BEGINNING OF THE MISSION DUE TO THE SUN ANGLE.

B. 9R SIDE: A MINUS DENSITY STREAK IS PRESENT 0.6" FROM AND PARALLEL TO THE INBOARD EDGE ON FRAMES 58 THROUGH 133. NUMEROUS FINE SCRATCHES ACROSS THE ENTIRE FORMAT AND PARALLEL TO THE MAJOR AXIS ARE NOTED ON ALL FRAMES BETWEEN THE HEAT SPLICES MADE THROUGH FRAMES 577 AND 1123. A MANUFACTURER'S SPLICE IS PRESENT THROUGH FRAME 50 AND ASSOCIATED WITH THIS SPLICE IS SOME DENDRITIC STATIC ON FRAMES 49, 50, 53 AND SOME FOGGING ON FRAME 52.

C. 9L SIDE: TWO ROWS OF MINUS DENSITY DOTS ARE PRESENT 3.2" AND 4.52" RESPECTIVELY FROM AND PARALLEL TO THE OUTBOARD EDGE OF THE FILM AND THEY ARE SPACED 1.55" APART. NUMEROUS FINE SCRATCHES ACROSS THE ENTIRE FORMAT AND PARALLEL TO THE MAJOR AXIS ARE NOTED ON ALL FRAMES BETWEEN THE BEGINNING OF THE MISSION AND THE

25X1

**SECRET**

Declassification Review by NGA/DoD

Excluded from automatic  
downgrading and  
declassification

-2-

HEAT SPLICE MADE THROUGH FRAME 441. ON THESE SAME FRAMES TWO HEAVY SCRATCHES ARE NOTED 3.65" AND 4.78" FROM AND PARALLEL TO THE INBOARD EDGE OF THE FILM. A HEAT SPLICE IS MADE THROUGH FRAME 1220. A MANUFACTURER'S SPLICE IS PRESENT THROUGH 1679 AND ASSOCIATED WITH THIS SPLICE THERE IS MINOR CREASING AND STATIC TRACES ON FRAMES 1679 AND 1680.

D. BOTH SIDES: A MINUS DENSITY STREAK IS NOTED 0.1" FROM AND PARALLEL TO THE INBOARD EDGES OF THE FILM THROUGHOUT THE MISSION. INBOARD EDGE FOG APPEARS INTERMITTENTLY HEAD TO TAIL. THERE ARE SEVERAL INSTANCES THROUGHOUT THIS MISSION WHERE DIRT, FOREIGN MATTER, BLISTERS, PINHOLES, SMALL EMULSION DIGS AND LIFTS ARE NOTED. THERE ARE MINOR PROCESSING STREAKS THROUGHOUT. THERE ARE 1905 FRAMES ON EACH SIDE OF THIS MISSION.

E. THERE ARE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING PROBLEMS OTHER THAN THOSE MENTIONED ABOVE.

3. POSITIVE:

- A. PI SUITABILITY IS GOOD.
- B. PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS OBSCURE APPROXIMATELY 50 PER CENT OF THIS MISSION.

S E C R E T

-END OF MESSAGE-

1